

**SECRET**

OSA-4144-64

9 SEP 1964

**MEMORANDUM FOR THE RECORD**

**SUBJECT: Trip Report, McCoy AFB, Orlando, Florida,  
31 August - 2 September 1964**

The Base Commander, Colonel James R. Wiley, conducted the tour of the base. The following observations were made:

**a. Hangar:**

Building 407 identified as the North Hangar was selected for the operation. The building has sufficient space to house project aircraft. Details concerning power, minor construction, etc. will be furnished by [REDACTED]

**b. PSEL:**

The Precision Measurement Equipment Lab presents itself as a neat, fully equipped activity capable of performing calibration and repair on practically all types of test gear. Support can be furnished without difficulty if required.

**c. POL:**

The POL facility is suitably located for convenient rail off-load and is in close proximity to the North Hangar. A small POL lab is situated near the fuel facility. The lab is available on a joint usage basis. There is sufficient dead trackage on the base for fuel storage. The unused trackage can accommodate twenty or more rail tank cars. Switching service from the storage area to the off-load site is available on a daily basis. The off-load site has a rail spur running parallel to the main POL hydrants. The spur will hold six tank cars. Off-loading PF-1A fuel into R-2 units from the spur will not interfere with the base POL function.

Oxygen - available

USAF review(s)  
completed.

Nitrogen - available

EDUCATION PC.

FOI 100

11 11

11 11

11 11

11 11

11 11

11 11

**SECRET**

EDUCATION PC.

FOI 100

11 11

25X1

**SECRET**

OSA-4144-64

d. Vehicles:

Transportation on base is limited. Vehicle rentals can be obtained through commercial or GSA rental agencies. GSA and commercial rental agency representatives are located on base.

e. Billeting:

Available quarters are adequate; however, the base can only provide quarters for one-half of the personnel involved. The remainder would have to seek quarters in motels or hotels off base.

f. Messing:

The dining halls are adequate for all personnel.

g. Other:

Office space is not available. Mention was made to the possibility of using trailers, or setting up within the hangar proper. Office furniture and equipment are not available. The base will purchase necessary items. We would have to provide the funds.

25X1

25X1

MD/OSA-DD/S&T: [REDACTED] (9 Sept 64)

Distribution:

Orig & 1 - D/FA/OSA  
1 - SS/OSA  
1 - CD/OSA  
1 - MD/OSA  
1 - R&F/OSA  
1 - COMMO/OSA  
1 - RB/OSA

**SECRET**